

Bay Creek Route Correction (111-50-10390)

Bay Creek was surveyed on June 22nd and 23rd to account for stream route accuracy. The present cataloged route is inconsistent with the actual route of the stream. The stream was trapped with baited minnow traps past the cataloged upper limit and resident Dolly Varden and cutthroat trout were the only species captured. No barrier to anadromous fish passage was found and the upper limit of this stream warrants further investigation, as noted on the following map. The table and map present trapping data and location of the updated stream route and features. Waypoint 1 and 2 represent the lower and upper limit of the updated route for the existing cataloged species.

WAYPOINT	LAT	LONG_	SPECIES	EFFORT
1	58.387058	-134.648145		
2	58.38957	-134.650309		
3	58.390394	-134.649846	DV	MINNOW TRAP
4	58.390463	-134.649608	DV	MINNOW TRAP
5	58.390704	-134.649446	DV, CT	MINNOW TRAP
6	58.391528	-134.647759	DV	MINNOW TRAP
7	58.391824	-134.647842	DV	MINNOW TRAP
8	58.392218	-134.647288	DV, CT	MINNOW TRAP
9	58.385233	-134.658566	DV	MINNOW TRAP



Figure 1: Dolly Varden and cutthroat trout captured at waypoint 5.



Figure 2: Cutthroat trout capture at waypoint 8.

Bay Creek Route Correction

